

---

This is a reproduction of a library book that was digitized by Google as part of an ongoing effort to preserve the information in books and make it universally accessible.

Google™ books

<https://books.google.com>



AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC HOLDER
PA-28-260, -32-300, -32R-300; T.C. A350	SA820GL	Installation of aileron and flap gap seals. Reissued 11/15/93.	CE-C	Blackhawk Airways, Inc. 4746 S. Columbia Drive Janesville, WI 53546
PA-30 Series; T.C. A1EA	SA72RM	Installation of camera wells. Amended 12/9/76.	RM	Horizons, Inc. P.O. Box 3134 Rapid City, SD 57701
PA-30 Series; T.C. A1EA	SA184EA	Installation of 13-quart alcohol propeller anti-icing kit utilizing either a Weldon pump (P/N 100B-6) or a Bendix pump (P/N 478360). Amended 10/15/71.	NE	Wiggins Airways, Inc. Norwood Municipal Arprt Norwood, MA 02062
PA-30 Series; T.C. A1EA	SA225EA	Installation of Monitair angle of attack and stall warning system. Reissued 2/14/72.	GL	Rosemount Engr. Co. 12001 W. 78th St. Eden Prairie, MN 55343
PA-30 Series; T.C. A1EA	SA233EA	Reservoir-type pneumatic wing and tail deicing system. Amended 10/7/70.	NE	R.W. Wiggins Airways Inc. Municipal Airport Norwood, MA 02062
PA-30 Series; T.C. A1EA	SA282CE	GUART System (Gear-up automatic response device).	GL	In-Flight Devices, Inc. 1621 W. Walnut St. Chicago, IL 60612
PA-30 Series; T.C. A1EA	SA343SW	Automatic pilot AK127, AK127E or AK127E-3, and lateral guidance radio coupler AK123.	SW	Mitchell Industries, Inc. P.O. Box 610 Municipal Airport Mineral Wells, TX 76067
PA-30 Series; T.C. A1EA	SA477EA	SAGA (semi-automatic gear actuating) system.	GL	In-Flight Devices Corp. 4885 Sawyer Road Int'l Airport Columbus, OH 43219
PA-30 Series; T.C. A1EA	SA520SO	Installation of Bendix FCS-810 (Piper Altimatec V/F/D) automatic flight control including manual electric trim and optional flight director indicator. Amended 8/13/76.	CE	Bendix Avionics Div P.O. Box 9414 Ft. Lauderdale, FL 33310
PA-30 Series; T.C. A1EA	SA531SW	Fifth seat.	SW	Nayak Aviation Corp. 206 East Terminal Dr. Int'l Airport San Antonio, TX 78216
PA-30; T.C. A1EA	SA533NW	Installation of aileron trim. Issued 10/19/77.	NW	Robert Smith Box 43 Okanagan Mission Kelowna, B.C., Canada

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC HOLDER
PA-30 Series; <i>T.C. AIEA</i>	SA534EA	Replacement of existing stall warning detector Safe Flight P/N C-52207 with pre-stall warning and speed control transducer, Safe Flight P/N 792 and speed control indicator, P/N 571.	EA	Safe Flt Instruments Corp New King Street White Plains, NY 10601
PA-30 Series; <i>T.C. AIEA</i>	SA559WE	B-4 flight control system including autopilot, PC-1 pitch assist, AH-1 altitude hold, and NAV-1 navigation coupler. Reissued October 1973.	SW	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-30 Series; <i>T.C. AIEA</i>	SA591CE	Install Alco XW20101-PA-30-L windshield wiper system.	CE	Alco Controls Corp. P.O. Box 12700 St. Louis, MO 63141
PA-30 Series; <i>T.C. AIEA</i>	SA727WE	Installation of Brittain Industries Model TT-5 wing tip fuel tanks. Reissued 9/17/87.	NM	John L. Osborne Star Route, Box 11 Oro Grande, CA 92368
PA-30 Series; <i>T.C. AIEA</i>	SA738CE	Install King Radio KNC 610 area navigation computer. Amended May 1974.	CE	King Radio Corp. Box 106 400 North Rogers Rd. Olathe, KS 66061
PA-30 Series; <i>T.C. AIEA</i>	SA766WE	Plastic wing tips replaced with "Speedplates" SP51463.	RM	Grand Valley Acft Inc. P.O. Box 158 Grand Junction, CO 81501
PA-30 Series; <i>T.C. AIEA</i>	SA767WE	Modification to include three pair of seat belts on rear seat to accommodate three passengers.	WE	Bates Aircraft, Inc. Municipal Airport Hawthorne, CA 90250
PA-30 Series; <i>T.C. AIEA</i>	SA776CE	Installation of King Radio KN-74 area navigation computer. Issued June 1971.	CE	King Radio Corp. Box 106 400 North Rogers Rd. Olathe, KS 66061
PA-30 Series; <i>T.C. AIEA</i>	SA789CE	Install Woodward propeller unfeathering accumulator kit number 213630. Reissued 3/20/92.	CE-C	Aircraft Systems, Inc. 5187 Falcon Road Rockford, IL 61109
PA-30 Series; <i>T.C. AIEA</i>	SA1154SW	Rudder and aileron interconnect system. Reissued 3/14/83.	SW	J.W. Miller Avn, Inc. HSB Box 7757 Marble Falls, TX 78654
PA-30; <i>T.C. AIEA</i>	SA1401CE	Install King Model KNS 80 digital area navigation system. Issued 2/16/78.	CE	King Radio Corp. 400 North Rogers Rd. Olathe, KS 66061
PA-30; <i>T.C. AIEA</i>	SA1696NM	Installation of Shadin 910502 "Digiflo" fuel flow indicator system and removal of fuel pressure indicating system. Reissued 3/17/88.	NM	John L. Osborne Star Route, Box 11 Oro Grande, CA 92368

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC HOLDER
PA-30 Series; <i>T.C. AIEA</i>	SA1935WE	Installation of Brittain flight control system Model B-5, NAV-2B, or B2C. Reissued 10/20/72.	SW	Brittain Industries, Inc. P.O. Box 51370 Tulsa, OK 74151
PA-30 S/N 30-1 thru 30-901; <i>T.C. AIEA</i>	SA2273NM	Installation of fiberglass window mouldings. Issued 4/16/84.	NM	Serv-Aero Engr., Inc. 37 Mortensen Avenue Salinas, CA 93905
PA-30; <i>T.C. AIEA</i>	SA3707WE	Installation of single piece windshield. Issued 8/7/78.	WE	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90806
PA-30; <i>T.C. AIEA</i>	SA3729WE	Installation of Hoskins Model CFS-2000, -2001, or FT-200 fuel flow indicating system. Reissued 4/1/90.	NM-L	Hoskins, Division of Sheldahl 15771 Red Hill Avenue Tustin, CA 92680-7303
PA-30; <i>T.C. AIEA</i>	SA4295SW	Propeller synchrophaser system. Issued 3/6/81.	SW	Richard D. Crow d/b/a Crow Aviation 3127 Laura Lee San Antonio, TX 78221
PA-30; <i>T.C. AIEA</i>	SA00160SE	Installation of modified instrument panel. Issued 12/12/94.	NM-SE	Ron and John's Comanche Svcs 2007 SE Ash Portland, OR 97214
PA-30, PA-39; <i>T.C. AIEA</i>	SA209GL	Installation of one piece windshield. Reissued 6/26/84.	CE	Great Lakes Aero Products 2412 Davison Road Flint, MI 48506
PA-30, PA-39; <i>T.C. AIEA</i>	SA271GL	Installation of Great Lakes forward windows, P/N's W-, W/T-, W/G-2058-187 or -250 and W-, W/G-20599-187 or -250. Reissued 6/26/84.	CE	Great Lakes Aero Products 2412 Davison Road Flint, MI 48506
PA-30, -39; <i>T.C. AIEA</i>	SA428NE	Installation of William C. Roberts brake discs P/N 202-22SS in lieu of Piper brake discs P/N 754-554. Amended 7/18/91.	NE	William C. Roberts 5 Lynbrook Lane Doylestown, PA 18901
PA-30, PA-39; <i>T.C. AIEA</i>	SA516GL	Installation of aileron, flap, flap to fuselage, rudder gap seals, wing root fairings, dorsal fin, and engine nacelle fairing. Reissued 5/29/90.	CE-C	Knots 2U, Inc. P.O. Box 589 Harbor Springs, MI 49740
PA-30, PA-39; <i>T.C. AIEA</i>	SA557GL	Installation of TRW Hartzell Propeller Models HC-E2YL-2BSF/ F7663-6Q and HC-E2YL-2BLSF/ /FJ7663-6Q used with Lycoming engine models IO-320-B1A or IO-320-C1A turbocharged and LIO-320-B1A or LIO-320-C1A turbocharged respectively. Amended 11/12/81.	GL	Universal Products, Inc. 645 Helke Road Vandalia, OH 45377

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC HOLDER
PA-30, -39; <i>T.C. AIEA</i>	SA634NE	Installation of Cleveland Wheel & Brakes (Parker Hannifin). Issued 2/21/89.	NE	Airparts of Lock Haven W.T. Piper Airport Box 418 Lock Haven, PA 17745
PA-30, PA-39; <i>T.C. AIEA</i>	SA673EA	Installation of radome kit 3058X. Amended 5/26/76.	GL	Norton Company Plastics & Synthetics Div Aero Products Operations P.O. Box 350 Akron, OH 44309
PA-30, PA-39; <i>T.C. AIEA</i>	SA676EA	Installation of Norton Company radome kit 3058-B. Amended 3/24/71.	GL	Norton Company Plastics & Synthetics Div Aero Products Operations P.O. Box 1187 Akron, OH 44309
PA-30, PA-39; <i>T.C. AIEA</i>	SA787WE	Installation of turbosupercharged Lycoming IO-320-B1A, IO-320-C1A or LIO-320-B1A or LIO-320-C1A engines. Reissued 10/23/87.	NM-L	Roto-Master, A Unit of Allied Signal, Inc. 7101 Fair Avenue N. Hollywood, CA 91605
PA-30, PA-39; <i>T.C. AIEA</i>	SA848EA	Installation of pneumatic pump operated wing and tail de-icing boot system. Issued 10/22/70.	NE	E.W. Wiggins Airways Inc. Norwood Municipal Arprt Norwood, MA 02062
PA-30, PA-39; <i>T.C. AIEA</i>	SA875GL	Install speed sweep windshield. Amended 6/24/87.	CE	Knots 2U, Inc. 1941 Highland Ave. Wilmette, IL 60091
PA-30, -39; <i>T.C. AIEA</i>	SA1111SW	Outer wing integral auxiliary fuel tanks and increase gross weight of 180 pounds. Amended 3/14/83.	SW	J.W. Miller Avn, Inc. HSB Box 7757 Marble Falls, TX 78654
PA-30, -39; <i>T.C. AIEA</i>	SA1112SW	Dorsal fin. Amended 3/14/83.	SW	J.W. Miller Avn, Inc. HSB Box 7757 Marble Falls, TX 78654
PA-30, -39; <i>T.C. AIEA</i>	SA1113SW	Extended nose with baggage compartment. Amended 3/14/83.	SW	J.W. Miller Avn, Inc. HSB Box 7757 Marble Falls, TX 78654
PA-30, -39; <i>T.C. AIEA</i>	SA1114SW	Nacelle baggage compartments. Amended 3/14/83.	SW	J.W. Miller Avn, Inc. HSB Box 7757 Marble Falls, TX 78654
PA-30, -39; <i>T.C. AIEA</i>	SA1151SW	Lycoming IO-360-C1C engines (200 hp) with Hartzell HC-C2YK-2/ C7666A-4 propeller. Amended 3/14/83.	SW	J.W. Miller Avn, Inc. HSB Box 7757 Marble Falls, TX 78654
PA-30, PA-39; <i>T.C. AIEA</i>	SA1239SW	Turbosupercharged Lycoming IO-360-C1C engines. Reissued 3/14/83.	SW	J.W. Miller Avn, Inc. HSB Box 7757 Marble Falls, TX 78654

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC HOLDER
PA-30, PA-39; T.C. A1EA	SA1254SW	Electrothermal propeller de-icing system. Reissued 3/14/83.	SW	J.W. Miller Avn, Inc. HSB Box 7757 Marble Falls, TX 78654
PA-30, PA-39; T.C. A1EA	SA1320CE	Chrome-plated brake disc installation. Amended 6/20/77.	CE	Engineering Plating and Processing, Inc. 641 Southwest Blvd Kansas City, KS 66103
PA-30, -39; T.C. A1EA	SA1337SW	Pneumatic de-icing system. Amended 3/14/83.	SW	J.W. Miller Avn, Inc. HSB Box 7757 Marble Falls, TX 78654
PA-30, PA-39; T.C. A1EA	SA1341SW	Nose taxi light. Reissued 3/14/83.	SW	J.W. Miller Avn, Inc. HSB Box 7757 Marble Falls, TX 78654
PA-30, PA-39; T.C. A1EA	SA1431NM	Installation of a Shadin 910502 or 910514 "Digiflo" digital fuel flow indicator system and optional removal of the fuel pressure indicating system on Piper PA-30 and PA-39 airplanes equipped with Lycoming Model IO-320-B1A and LIO-320-B1A or IO-320-C1A and LIO-320-C1A engines. Reissued 3/1/88.	NM	J. L. Osborne Star Route, Box 11 Oro Grande, CA 92368
PA-30, -39; T.C. A1EA	SA1530GL	Install PA-30 or PA-39 lower cowl oil drain access panel with relief for quick drain. Amended 3/1/91.	CE-C	Aztec Air Service, Inc. 3739 Cottontail Lane Shelby Twp., MI 48316
PA-30, PA-39; T.C. A1EA	SA1662GL	Installation of rudder fin cap fairing, with or without a strobe. Issued 11/20/91.	CE-C	Knots 2U, Inc. P.O. Box 589 Harbor Springs, MI 49740
PA-30, -39; T.C. A1EA	SA1712GL	Installation of Gear Lobe fairings. Issued 3/23/92.	CE-C	Knots 2U, Inc. P.O. Box 589 Harbor Springs, MI 49740
PA-30, PA-39; T.C. A1EA	SA1754NM	Installation of a Shadin 910502 or 910514 "Digiflo" digital fuel flow indicator system and removal of the pressure indicating system on PA-30 and PA-39 airplanes equipped with Lycoming IO-320-B1A and LIO-320-B1A engines. Amended 2/7/83.	NM	Comanche Aaft Products Co P.O. Box 418 Bothel, WA 98011
PA-30, PA-39; T.C. A1EA	SA1756NM	Installation of positive flap retraction system. Amended 4/10/90.	SW	Sierra Industries, Inc. P.O. Box 5184 Uvalde, TX 78802-5184

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC HOLDER
PA-30, PA-39; <i>T.C. AIEA</i>	SA2312WE	Installation of leading edge cuffs, stall fences, stall strips drooped ailerons, flap actuated stabilator trim system, raked wing tips (optional) and dorsal fin. Reissued 10/10/86.	SW	Sierra Industries, Inc. P.O. Box 5184 Uvalde, TX 78802
PA-30, -39; <i>T.C. AIEA</i>	SA2484CE	Installation of side windows with an increase of thickness from 1/8 inch to 1/4 inch. Issued 4/14/89.	CE-W	Robert A. Weber Route 4, Box 13A Newton, KS 67114
PA-30, -39; <i>T.C. AIEA</i>	SA2550CE	Installation of a Webco door latch kit per Webco Aircraft Drawing List 2430-101. Issued 10/27/89.	CE-W	Webco Aircraft Route 4, Box 13A Newton, KS 67114
PA-30, -39; <i>T.C. AIEA</i>	SA2647CE	Installation of flap actuated gear warning system. Issued 8/16/90.	CE-W	Platte Valley Aero Route 1, Box 250 Platte City, MO 64079
PA-30, PA-39; <i>T.C. AIEA</i>	SA2652CE	Installation of main fuel cell bladders as replacements for original bladders. Reissued 7/22/94.	SW	DuraFlex Fuel Cells Corp 103 Centennial Drive Hot Springs, AR 71913
PA-30, PA-39; <i>T.C. AIEA</i>	SA2849WE	Installation of oxygen system. Reissued 1/26/84.	CE	Sky-Ox Limited P.O. Box 6 Saint Joseph, MI 49085
PA-30, -39; <i>T.C. AIEA</i>	SA3105SO	Installation of "speed spats" main landing gear fairings. Issued 12/18/91.	CE-A	LoPredti Speed Merchants 260 Seagull Avenue Vero Beach, FL 32960
PA-30, PA-39; <i>T.C. AIEA</i>	SA3128SW-D	Mitchell automatic flight system AK598, consisting of Century III autopilot with optional command automatic trim, radio, and glide slope couplers. Reissued 6/5/84.	SW	Century Flt Systems, Inc. F.M. 1195, P.O. Box 610 Mineral Wells, TX 76067
PA-30, PA-39; <i>T.C. AIEA</i>	SA3205NM	Installation of fiberglass wing tips. Issued 12/6/85.	NM	Johnston Aft Svc., Inc. P.O. Box 1457 Tulare, CA 93275
PA-30, -39; <i>T.C. AIEA</i>	SA3282SO	Installation of flap bracket fairings. Issued 7/13/92.	CE-A	LoPresti Speed Merchants 3215 26th Avenue Vero Beach, FL 32960
PA-30, -39; <i>T.C. AIEA</i>	SA3302SO	Installation of fiberglass nose bowl. Amended 3/4/93.	CE-A	LoPresti Speed Merchants 260 Seagull Avenue Vero Beach, FL 32960
PA-30, PA-39; <i>T.C. AIEA</i>	SA3336WE	Installation of single piece windshield. Issued 2/2/77.	WE	Wayne Airframe, Inc. 16644 Roscoe Blvd Van Nuys, CA 91406

AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC HOLDER
PA-30, PA-39; T.C. A1EA	SA3395SW-D	Installation of Mitchell automatic system AK893 consisting of Century IIB autopilot. Reissued 8/24/83.	SW	Century Flt Systems, Inc. F.M. 1195, P.O. Box 610 Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA3468SW-D	Installation of Century automatic flight system Model AK974 consisting of a Century 2010/2030/2031/2050/2051 autopilot. Amended 10/21/92.	SW	Century Flt. Systems, Inc. F.M. 1195, P.O. Box 610 Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA3563NM	Installation of ARNAV Systems FC-10/FT-10 digital fuel flow indicating systems. Issued 9/14/87.	NM	ARNAV Systems, Inc. 26810 Oak Avenue Suite J Canyon Country, CA 91351
PA-30, PA-39; T.C. A1EA	SA4066WE	Installation of Silver Instruments Fueltron III G or III P digital fuel flow and totalizer system. Reissued 4/29/91.	NM-S	Arnav Systems, Inc. 22007 Meridian East Graham, WA 98338
PA-30, PA-39; T.C. A1EA	SA4189WE	Installation of DTL-1000, -1001 and/or -1002/3 autopilot adapters for the Edo-Aire Mitchell Century III autopilot. Issued 7/29/80.	WE	Douglas L. Kettler 1212 N. Broadway, Apt. H Escondido, CA 92026
PA-30, 39; T.C. A1EA	SA4852NM	Installation of electrical heater, including engine driven alternators and controls. Issued 4/4/90.	NM	Innovative Scientific Development, Inc. 2003 Aviation Dr. #19 Corona, CA 91720
PA-30, PA-39; T.C. A1EA	SA5112SW-D	Installation of S-TEC System 60 two axis automatic flight guidance system Model ST-127 with optional automatic electric trim system. Amended 6/16/87.	SW	S-TEC Corporation Route 4, Building 946 Wolters Ind Complex Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA5138SW-D	S-TEC System 60 pitch stabilization ST-128 with optional automatic electric trim. Issued 2/28/83.	SW	S-TEC Corporation Route 4, Building 946 Wolters Ind Complex Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA6058SW-D	Installation of S-TEC manual electric trim system, Model ST-355. Issued 3/19/86.	SW	S-TEC Corporation Route 4, Building 946 Wolters Ind Complex Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA7151SW-D	Installation of S-TEC System 65 two axis automatic flight guidance system, Model ST-414. Issued 5/11/87.	SW	S-TEC Corporation Route 4, Building 946 Wolters Ind. Complex Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA00449AT	Installation of flap gap seals. Issued 3/31/94.	CE-A	LoPresti Speed Merchants 3426 26th Avenue Vero Beach, FL 32960



AIRCRAFT MAKE MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC HOLDER
PA-30, PA-39; T.C. A1EA	SA214CH	Installation of Hartzell HC-E2YL-2BSF/F7663D-4 or HC-E2YL-2BLSF/FJ7663D-4 model propellers. Issued 6/17/94.	CE-C	Knots 2 U, Inc. P O Box 589 Harbor Springs, MI 49740
PA-30, PA-39; T.C. A1EA	SA215CH	Installation of an induction system. Issued 6/17/94.	CE-C	Knots 2 U, Inc. P O Box 589 Harbor Springs, MI 49740
PA-30, -39, -40; T.C. A1EA	SA1533GL	Installation of on-board engine analyzer system. Issued 11/30/90.	CE-C	Masten Products Inc. 713 W. Ellsworth Road Suite A Ann Arbor, MI 48108
PA-30, PA-39, PA-40; T.C. A1EA	SA4238WE	Installation of inflatable door seal. Issued 9/25/80.	WP	Bob Fields Aerocessories 5673 Stanford St. Ventura, CA 93003
PA-30, PA-39; T.C. A1EA	SA5227SW-D	S-TEC System 40/50 single and two axis automatic flight guidance system ST-205-40/50.	SW	S-TEC Corporation Route 4, Building 946 Wolters Ind Complex Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA8891SW-D	Installation of S-TEC System 55 two axis automatic flight guidance system, Model ST-562, with optional automatic electric trim system. Issued 11/15/94.	SW	S-TEC Corporation 946 Pegram Mineral Wells, TX 76067
PA-30, PA-39; T.C. A1EA	SA00670AT	Installation of an OCEM AP-2C or AP-3C autopilot system. Issued 2/28/95.	CE-A	OCEM Avionics Corporation 1108 NW 36th Drive Gainesville, FL 32605
PA-30 (s/n 30-2 thru 30-2000); PA-39 (s/n 39-1 thru 39-155);	SA1022NE	Installation of single pane increased thickness side windows. Issued 10/22/92.	NE	L.P. Aero Plastics, Inc. RD #1, Box 201B Jeannette, PA 15644
PA-30, PA-39, PA-40 Series; T.C. A1EA	SA5841NM	Installation of an engine electronic digital tachometer. Issued 9/30/92.	NM-L	Horizon Instruments, Inc. 556 S. State College Blvd Fullerton, CA 92631
PA-31 (S/N 31-2 and up); T.C. A8EA	SA142RM	Install Model CFS-2000 fuel flow meter and related systems. Reissued 4/1/90.	NM-L	Hoskins, Division of Sheldahl 15771 Red Hill Avenue Tustin, CA 92680-7303
PA-31; T.C. A8EA	SA191GL	Installation of microwave landing airborne equipment. Reissued 1/12/79.	CE	Wilcox Electric, Inc. 1400 Chestnut Kansas City, MO 64127
PA-31 Series; T.C. A20SO	SA367GL	Installation of Norton radome kit No. 2032X Amended 10/24/80.	GL	Norton Company Plastics & Synthetics Div Aero Products Operations P.O. Box 350 Akron, OH 44309